Senior Services Municipal Building Renovation 2023 INVITATION TO BID

OWNER – The OWNER of the project is Covert Township, 73943 Lake St, PO BOX 35, Covert, MI 49043, (269) 764-8986. Project documents can be viewed at the Township Hall and the Township Website, Coverttwp.com.

PROJECT – The Project consists primarily of renovating the interior of an 1800 sq ft bank building located at 33800 M-140, Covert, MI 49043, to be used for government services. A commercial inspection report and conceptual drawings are attached to this invitation to bid. A walk through of the building can be arranged upon request. The work includes, but is not limited to, the following:

- Remove approximately 40 linear feet of wall and various closets
- Adjust drop ceiling as needed
- Remove various attached counters, cabinetry and sinks
- Remove bank vault door and replace with standard door.
- Remove old security system and other bank mechanical equipment
- Repair several windows
- Replace light fixtures as needed
- Repair and install communication lines as needed
- Convert a storage space into an ADA restroom
- Make modifications as needed to ensure ADA compliance
- Inspect mechanical, plumbing and electrical systems for possible repair or replacement
- Install an alternative entrance with vestibule and ADA sidewalk in rear of building
- Repair and paint drywall, and replace carpet throughout
- Install signage
- Install intercom and security system
- Install counters, backsplash, cabinets, sink, oven, and refrigerator in kitchenette
- Upgrade drinking fountain
- Minor paint and repair of building exterior
- Repair of sidewalk and minor landscaping
- Submit samples for asbestos testing and abatement if necessary

NOTICE: Proposal for service will be received until noon on January 10, 2022, in the Covert Township Clerk's Office at the Covert Township Hall, 3943 Lake St, PO BOX 35, Covert, MI 49043, requesting quotations for supplying the Township with the item(s) listed herein and as further specified. These proposals will be publicly opened in a meeting of the Covert Township Board of Trustees on a date to be noticed to the public.

HOW TO SUBMIT PROPOSAL: All proposals shall be submitted in sealed opaque envelopes, mailed to the Covert Township Clerk at the Covert Township Hall, PO BOX 35, Covert, MI 49043, or delivered in person the office of the Covert Township Clerk, 3943 Lake St, Covert, MI 49043 and marked on the outside of the envelopes as follows:

SEALED PROPOSAL FOR: Senior Services Municipal Building Renovation 2023

Any proposal transmitted to Covert Township's facsimile (fax) machine or email will be deemed <u>an</u> <u>invalid bid and not be considered for review.</u> It will be the bidder's sole responsibility to ensure that

Senior Services Municipal Building Renovation 2023 INVITATION TO BID

their proposal reaches the Covert Township Clerk's office on or before the closing hour and date shown above.


PURPOSE OF PROPOSAL: Covert Township intends to secure a supply source for the services(s) defined by considering (but not limited to) the following: lowest price, terms of the warranty, and prompt and convenient service by the supplier to the Township. Any failure on the part of the supplier or contractor to comply with the following conditions and specifications shall be a reason for contract termination. The Township reserves the right to award the supplier where the service meets the specification, terms, and conditions. The Township Board of Trustees considers the bid to be in the Township's best interest.

FUNDING SOURCE: Funding for this project is provided, in part, by the Covert Township millage for Activities or Services for Older Persons. A portion of the project will also be funded by the Covert Township General Fund.

Naomi Barnes Covert Township Clerk 3943 Lake Street, PO BOX, Covert, MI 49043 Office: (269) 764-8986 Ext. 3 Clerk@coverttwp.com


Covert Township Senior Services Municipal Building

CURRENT LAYOUT




Covert Township Senior Services Municipal Building

PROPOSED MODIFICATIONS



Covert Township Senior Services Municipal Building





TRU-SPECT INSPECTIONS & ENVIRONMENTAL

(269)414-0469 greg@tru-spect.com http://www.tru-spect.com



RESIDENTIAL

33380 M-140 Covert, MI 49043

Covert Township OCTOBER 3, 2022



Inspector
Josh Hill
InterNachi Certified #NACHI18120509
(269)414-0337
josh@tru-spect.com

TABLE OF CONTENTS

1: Inspection Details	5
2: Roof	6
3: Exterior	8
4: Basement, Crawlspace & Structure	15
5: Attic	16
6: HVAC	18
7: Electrical	20
8: Plumbing	21
9: Vault Room	23
10: Exam Room 1	25
11: Exam Room 2	28
12: Treatment Room	32
13: Mechanical Room	34
14: Bathroom 1	38
15: Lobby	41
16: Office	44
17: Main Floor Hallway	46
18: Main Floor Hallway 2	48
19: Foyer	50
Standard of Practice	51

SUMMARY









ITEMS INSPECTED

MAINTENANCE ITEM

RECOMMENDATION

- 2.1.1 Roof Coverings: Damaged (General)
- 2.1.2 Roof Coverings: Exposed nails.
- 3.3.1 Exterior Exterior Faucet: Spigot is missing handle
- 3.4.1 Exterior Electrical (Outlets, Fixtures, Switches): Light Inoperable
- 3.4.2 Exterior Electrical (Outlets, Fixtures, Switches): Debris inside receptacle
- 3.5.1 Exterior Cooling Equipment: Damaged fins
- 3.6.1 Exterior Siding, Flashing & Trim: Spalling brick
- 3.7.1 Exterior Decks, Balconies, Porches & Steps: Damaged support column
- 3.8.1 Exterior Exterior Doors: Door Sill/Trim
- 3.10.1 Exterior Eaves, Soffits & Fascia: Paint/Finish Failing
- 3.12.1 Exterior Walkways, Patios & Driveways: Sidewalk Trip Hazard
- 3.13.1 Exterior Vegetation, Grading and Drainage: Tree Overhang
- 3.13.2 Exterior Vegetation, Grading and Drainage: Vegetation on siding
- 5.2.1 Attic Framing : Moisture staining.
- △ 5.3.1 Attic Electrical: Live wites outside of junction box
- 5.5.1 Attic Bathroom Exhaust : Bathroom vents into attic
- 6.1.1 HVAC Heating Equipment: Leaking humidifier
- 9.4.1 Vault Room Floors: Carpet Stains
- 10.3.1 Exam Room 1 Lighting Fixtures, Switches & Receptacles: Outlet loose
- 10.3.2 Exam Room 1 Lighting Fixtures, Switches & Receptacles: Wires tied outside of junction box
- № 10.5.1 Exam Room 1 Windows: Missing Screen
- 10.5.2 Exam Room 1 Windows: Window is screwed shut
- 10.6.1 Exam Room 1 Walls: Minor damage
- 11.3.1 Exam Room 2 Lighting Fixtures, Switches & Receptacles: No GFCI protection
- 11.4.1 Exam Room 2 Floors: Carpet Stains
- 2 11.5.1 Exam Room 2 Windows: Missing Screen
- 11.5.2 Exam Room 2 Windows: Chipping paint
- 11.5.3 Exam Room 2 Windows: Window is screwed shut

- 11.6.1 Exam Room 2 Walls: Minor Damage
- 11.7.1 Exam Room 2 Ceilings: Minor Damage
- 11.7.2 Exam Room 2 Ceilings: Moisture Staining/Damage
- 12.3.1 Treatment Room Lighting Fixtures, Switches & Receptacles: Damaged receptacle
- 12.4.1 Treatment Room Floors: Moderate Wear
- 12.4.2 Treatment Room Floors: Flooring possibly asbestos
- 2 12.5.1 Treatment Room Windows: Missing Screen
- 13.3.1 Mechanical Room Lighting Fixtures, Switches & Receptacles: Missing light fixture cover
- 13.3.2 Mechanical Room Lighting Fixtures, Switches & Receptacles: Light flickers when on
- 13.4.1 Mechanical Room Floors: Damaged (General)
- 13.4.2 Mechanical Room Floors: Flooring possibly asbestos
- 2 13.5.1 Mechanical Room Windows: Missing Screen
- 13.5.2 Mechanical Room Windows: Window is screwed shut
- 13.8.1 Mechanical Room Doors: Door does not close
- 14.4.1 Bathroom 1 GFCI & AFCI: No GFCI Protection Installed
- 14.5.1 Bathroom 1 Exhaust Systems: Vent needs cleaning
- 14.6.1 Bathroom 1 Floors: Damaged (General)
- 14.6.2 Bathroom 1 Floors: Flooring possibly asbestos
- 2 15.5.1 Lobby Windows: Missing Screen
- 15.5.2 Lobby Windows: Broken glass
- 15.5.3 Lobby Windows: Window is screwed shut
- 16.6.1 Office Walls: Minor cracks
- 16.6.2 Office Walls: Damage
- 16.9.1 Office Closets: Minor damage
- 17.6.1 Main Floor Hallway Walls: Minor cracks
- 18.3.1 Main Floor Hallway 2 Lighting Fixtures, Switches & Receptacles: Damaged receptacle

1: INSPECTION DETAILS

Information

In AttendanceStyleType of BuildingInspectorCommercialCommercial

Temperature (approximate) Weather Conditions

51 Fahrenheit (F) Clear

Occupancy

Partial

Houses that occupied limit the visibility throughout the house for outlets, flooring areas, areas of wall, ECT. We can only Inspect what is visible.

2: ROOF

		IN	NI	NP	D
2.1	Coverings	Χ			Χ
2.2	Layers	Χ			
2.3	Ventilation	Χ			
2.4	Plumbing Vent	Χ			

IN = Inspected

NI = Not Inspected NP = Not Present

D = Deficiency

Information

Roof Type/Style

Gable

Plumbing Vent: Present



Coverings: Material Asphalt

Plumbing Vent: Amount

Layers: Layers

Inspection Method Roof











Ventilation: Ventilation Type

Gable Vents, Soffit Vents, Thermostatically Controlled Fan







Observations

2.1.1 Coverings

DAMAGED (GENERAL)




Recommend a qualified roofing contractor evaluate and repair as needed.




2.1.2 Coverings

EXPOSED NAILS.

through your roof.



Recommend covering with tar or silicone to prevent moisture intrusion.



3: EXTERIOR

		IN	NI	NP	D
3.1	Foundation		Χ		
3.2	Service Entrance Conductors	Χ			
3.3	Exterior Faucet	Χ			Χ
3.4	Electrical (Outlets, Fixtures, Switches)	Χ			Χ
3.5	Cooling Equipment	Χ			Χ
3.6	Siding, Flashing & Trim	Χ			Χ
3.7	Decks, Balconies, Porches & Steps	Χ			Χ
3.8	Exterior Doors	Χ			Χ
3.9	Windows	Χ			
3.10	Eaves, Soffits & Fascia	Χ			Χ
3.11	Gutter System			Х	
3.12	Walkways, Patios & Driveways	Χ			
3.13	Vegetation, Grading and Drainage	Χ			Χ

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiency

Information

Foundation: Material

Service Entrance Conductors: Slab on Grade **Electrical Service Conductors Below Ground**



Siding, Flashing & Trim: Siding Material Brick

Cooling Equipment: Energy Source/Type Electric

Decks, Balconies, Porches & **Steps: Type**

Front Entryway, Covered Patio



Cooling Equipment: Location

Exterior North

Decks, Balconies, Porches &

Steps: MaterialConcrete, Asphalt

Windows: Window Material

Wood

Inspection Method

Visual

Exterior Doors: Exterior Entry

Door

Steel, Wood

Eaves, Soffits & Fascia: Type

Wood

Windows: Window Type

Double-hung

Gutter System: Gutter Material

Not present









Exterior Faucet: General

2





Cooling Equipment: Brand

Arcoaire









Walkways, Patios & Driveways: Driveway Material Asphalt, Concrete





Limitations

Foundation

FOUNDATION NOT VISIBLE

Cooling Equipment

LOW TEMPERATURE

The A/C unit was not tested due to low outdoor temperature. This may cause damage the unit.

Observations

3.3.1 Exterior Faucet

SPIGOT IS MISSING HANDLE







3.4.1 Electrical (Outlets, Fixtures, Switches)

Recommendation

LIGHT INOPERABLE

One or more lights are not operating. New light bulb possibly needed.









3.4.2 Electrical (Outlets, Fixtures, Switches)

DEBRIS INSIDE RECEPTACLE

Recommend repair or replacement.





3.5.1 Cooling Equipment

DAMAGED FINS

Recommend further evaluation by qualified HVAC technician.





3.6.1 Siding, Flashing & Trim



SPALLING BRICK

Suggest resealing brick to keep further spalling from occurring.



3.7.1 Decks, Balconies, Porches & Steps

DAMAGED SUPPORT COLUMN

Recommend repair or replacement.





3.8.1 Exterior Doors

DOOR SILL/TRIM



Door sill and/or trim is loose, deteriorated or worn and repair or replacement should be considered.







3.10.1 Eaves, Soffits & Fascia

PAINT/FINISH FAILING



The paint or finish is failing. This can lead to deterioration and rot of the material. Recommend that the araes be properly prepared and painted / finished.











3.12.1 Walkways, Patios & Driveways

Recommendation

SIDEWALK TRIP HAZARD

Trip hazards observed. Patch or repair recommended.



3.13.1 Vegetation, Grading and Drainage



TREE OVERHANG

Trees observed overhanging the roof. This can cause damage to the roof and prevent proper drainage. Recommend a qualified tree service trim to allow for proper drainage.



3.13.2 Vegetation, Grading and Drainage



VEGETATION ON SIDING

Vegetation on siding may cause premature failure.



4: BASEMENT, CRAWLSPACE & STRUCTURE

		IN	NI	NP	D
4.1	Basements & Crawlspaces			Χ	
4.2	Lighting Fixtures, Switches & Receptacles		Χ		
4.3	Steps, Stairways & Railings			Χ	
4.4	Floor		Χ		
4.5	Columns			Χ	
4.6	Joist		Χ		
4.7	Beam		Χ		
4.8	Foundation		Χ		
4.9	Windows			Χ	

Information

Basements & Crawlspaces: Type Floor : Material Floor : Sub-floor
Slab on Grade Inaccessible Not visible

Columns : TypeJoist: TypeBeam: TypeNot presentUnknownUnknown

Foundation: Type Windows: Window Type Windows: Window Material

Poured Concrete Not present Not present

5: ATTIC

		IN	NI	NP	D
5.1	Access Location	Χ			
5.2	Framing	Χ			Χ
5.3	Electrical	Χ			Χ
5.4	Insulation	Χ			
5.5	Bathroom Exhaust	Χ			Χ

IN = Inspected

NI = Not Inspected NP = Not Present

D = Deficiency

Information

Access Location: Access type Hatch

Framing: Sheething Plywood



Framing: Framing Trusses



Insulation: Insulation **Fiberglass**



Bathroom Exhaust: Bathroom Exhaust Fan

Vented Into Attic

Access Location: Location Mechanical Room





Observations

5.2.1 Framing

MOISTURE STAINING.



Area of moisture staining. No moisture detected at the time of the inspection.





5.3.1 Electrical

LIVE WITES OUTSIDE OF JUNCTION BOX





5.5.1 Bathroom Exhaust

BATHROOM VENTS INTO ATTIC



The bathroom vent exhausts inside the attic. This may cause excessive moisture buildup inside the attic which in turn may cause fungal growth. Recommend running pipe so vent exhausts outside.



6: HVAC

		IN	NI	NP	D
6.1	Heating Equipment	Χ			Χ

Heating Equipment: Heat Type

Forced Air

IN = Inspected

NI = Not Inspected NP = Not Present

Metal

Heating Equipment: Ductwork

D = Deficiency

Information

Heating Equipment: Energy

Source

Natural Gas


Heating Equipment: Manufacture

Date

Unknown

Heating Equipment: Brand

Luxaire



Heating Equipment: Attachments

Humidifier, Central Air





Observations

6.1.1 Heating Equipment

LEAKING HUMIDIFIER



The humidifier leaks substantially when the furnace is on. Recommend further evaluation and repair by a qualified HVAC technician.



7: ELECTRICAL

		IN	NI	NP	D
7.1	Main Panel	Χ			
7.2	Branch Wiring Circuits, Breakers & Fuses	Χ			
7.3	Building Receptacles	Χ			

Information

Main Panel: Main Panel Location

Mechanical Room

Branch Wiring Circuits, Breakers & Fuses: Branch Wire 15 and 20 AMP

Copper

Main Panel: Panel Manufacturer

Square D

Main Panel: Panel Capacity
200 AMP

Branch Wiring Circuits, Breakers & Fuses: Wiring Method Romex Main Panel: Panel Type
Circuit Breaker

Building Receptacles: Grounded

Outlets Yes







8: PLUMBING


		IN	NI	NP	D
8.1	Main Water Supply	Χ			
8.2	Distribution piping	Χ			
8.3	Waste Plumbing		Χ		
8.4	Water Heater	Χ			
8.5	Sump Pump			Χ	
8.6	Water Softener			Х	

Information

Main Water Supply: Water Source Main Water Supply: Location
Public Mechanical Room



Distribution piping: TypeCopper



Waste Plumbing: Type
Not visible

Water Heater: Location
Mechanical Room

Water Softener : Location

Not Present

Water Heater: Power Source/Type Water Heater: Capacity
Gas 40 gallons

Water Heater: Manufacture Date Sump Pump: Location 02/08/2016 Not Present

Water Heater: Manufacturer

Richmond

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

Here is a nice maintenance guide from Lowe's to help.



Limitations

Waste Plumbing

NO WASTE PLUMBING WAS VISIBLE AT TIME OF INSPECTION.

9: VAULT ROOM


		IN	NI	NP	D
9.1	General	Χ			
9.2	Heating/ Cooling			Χ	
9.3	Lighting Fixtures, Switches & Receptacles	Χ			
9.4	Floors	Χ			Χ
9.5	Windows			Χ	
9.6	Walls	Χ			
9.7	Ceilings	Χ			
9.8	Doors	Χ			
9.9	Closets	Χ			
9.10	Smoke Detectors			Χ	

Not Present

Windows: Window Type

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings
Source Carpet



Walls: Wall Material
Concrete

Ceilings: Ceiling Material
Concrete

General: LocationMain Floor

Not Present

Windows: Window Material





Limitations

Doors

UNABLE TO ASSESS VAULT DOOR


Observations


9.4.1 Floors

CARPET STAINS



Carpet had areas of staining or discoloration. Recommend a thorough steam clean by a qualified carpet cleaning company





10: EXAM ROOM 1

		IN	NI	NP	D
10.1	General	Χ			
10.2	Heating/ Cooling	Χ			
10.3	Lighting Fixtures, Switches & Receptacles	Χ			Χ
10.4	Floors	Χ			
10.5	Windows	Χ			Χ
10.6	Walls	Χ			Χ
10.7	Ceilings	Χ			
10.8	Doors	Χ			
10.9	Closets			Χ	
10.10	Smoke Detectors			Χ	
10.11	Sink	Χ			

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings
Source Carpet



Walls: Wall MaterialDrywall

Windows: Window TypeDouble-hung



Ceilings: Ceiling MaterialDrywall

General: LocationMain Floor

Wood

Windows: Window Material





Sink: General





Observations

10.3.1 Lighting Fixtures, Switches & Receptacles



OUTLET LOOSE

Electrical strip was loose on the wall. Recommend refasting to the wall to prevent movement.



10.3.2 Lighting Fixtures, Switches & Receptacles

WIRES TIED OUTSIDE OF JUNCTION **BOX**





10.5.1 Windows

MISSING SCREEN

Window missing screen. Recommend replacement.

Maintenance Item



10.5.2 Windows







10.6.1 Walls

MINOR DAMAGE







11: EXAM ROOM 2

		IN	NI	NP	D
11.1	General	Χ			
11.2	Heating/ Cooling	Χ			
11.3	Lighting Fixtures, Switches & Receptacles	Χ			Χ
11.4	Floors	Χ			Χ
11.5	Windows	Χ			Χ
11.6	Walls	Χ			Χ
11.7	Ceilings	Χ			Χ
11.8	Doors	Χ			
11.9	Closets	Χ			
11.10	Smoke Detectors			Χ	

Wood

Windows: Window Material

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings Source Carpet



Ceilings: Ceiling MaterialSuspended Ceiling Panels

Walls: Wall MaterialDrywall

General: LocationMain Floor





Windows: Window Type

Double-hung





Observations

11.3.1 Lighting Fixtures, Switches & Receptacles

NO GFCI PROTECTION







11.4.1 Floors

CARPET STAINS

Carpet had areas of staining or discoloration. Recommend a thorough steam clean by a qualified carpet cleaning company





11.5.1 Windows

MISSING SCREEN

Window missing screen. Recommend replacement.



Safety Hazard





11.5.2 Windows

CHIPPING PAINT





11.5.3 Windows

WINDOW IS SCREWED SHUT



Recommendation

11.6.1 Walls

MINOR DAMAGE





11.7.1 Ceilings



MINOR DAMAGE

Minor damage or deterioration to the ceiling was visible at the time of the inspection.



11.7.2 Ceilings

MOISTURE STAINING/DAMAGE



No moisture detected at time of inspection. Unknown if issue has been resolved. Recommend asking seller if any repairs have been made.



12: TREATMENT ROOM

		IN	NI	NP	D
12.1	General	Χ			
12.2	Heating/ Cooling	Χ			
12.3	Lighting Fixtures, Switches & Receptacles	Χ			Χ
12.4	Floors	Χ			Χ
12.5	Windows	Χ			Χ
12.6	Walls	Χ			
12.7	Ceilings	Χ			
12.8	Doors	Χ			
12.9	Closets			Χ	
12.10	Smoke Detectors			Χ	

IN = Inspected

NI = Not Inspected NP = Not Present

D = Deficiency

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings Tile Source



Walls: Wall Material Drywall

Windows: Window Type Double-hung



Ceilings: Ceiling Material Suspended Ceiling Panels

General: Location Main Floor

Wood

Windows: Window Material





Observations

12.3.1 Lighting Fixtures, Switches & Receptacles

DAMAGED RECEPTACLE

Recommend replacement.







12.4.1 Floors

MODERATE WEAR



Floors in the room exhibited moderate surface wear along major paths of travel. Recommend a qualified flooring contractor evaluate.

12.4.2 Floors

FLOORING POSSIBLY ASBESTOS

Recommend testing before removal.





12.5.1 Windows

MISSING SCREEN

Window missing screen. Recommend replacement.






13: MECHANICAL ROOM

		IN	NI	NP	D
13.1	General	Χ			
13.2	Heating/ Cooling	Χ			
13.3	Lighting Fixtures, Switches & Receptacles	Χ			Χ
13.4	Floors	Χ			Χ
13.5	Windows	Χ			Χ
13.6	Walls	Χ			
13.7	Ceilings	Χ			
13.8	Doors	Χ			Χ
13.9	Closets			Χ	
13.10	Smoke Detectors			Χ	
13.11	Mop Sink	Χ			

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings
Source
Tile



Walls: Wall MaterialDrywall, Concrete

Windows: Window TypeDouble-hung




Ceilings: Ceiling MaterialDrywall

Mop Sink: General

Wood

Windows: Window Material



General: Location

Main Floor





Observations

13.3.1 Lighting Fixtures, Switches & Receptacles

MISSING LIGHT FIXTURE COVER






13.3.2 Lighting Fixtures, Switches & Receptacles

LIGHT FLICKERS WHEN ON

Recommend further evaluation by a qualified electrician.



13.4.1 Floors

DAMAGED (GENERAL)

The floor had general moderate damage visible at the time of the inspection. Recommend service by a qualified contractor.







13.4.2 Floors

FLOORING POSSIBLY ASBESTOS

Recommend testing before removal.





13.5.1 Windows

MISSING SCREEN

Window missing screen. Recommend replacement.





13.5.2 Windows

WINDOW IS SCREWED SHUT





13.8.1 Doors

DOOR DOES NOT CLOSE





14: BATHROOM 1

		IN	NI	NP	D
14.1	General	Χ			
14.2	Heating/ Cooling	Χ			
14.3	Lighting Fixtures, Switches & Receptacles	Χ			
14.4	GFCI & AFCI	Χ			Χ
14.5	Exhaust Systems	Χ			Χ
14.6	Floors	Χ			Χ
14.7	Windows			Χ	
14.8	Walls	Χ			
14.9	Ceilings	Χ			
14.10	Sink	Χ			
14.11	Toilet	Χ			
14.12	Doors	Χ			


Information

General: LocationMain Floor

Heating/ Cooling: Heating Cooling Exhaust Systems: Exhaust Fans SourceFan Only



Floors: Floor Coverings
Linoleum



Walls: Wall MaterialTile, Wallpaper

Windows: Window Type
Not Present

Windows: Window MaterialNot Present

Ceilings: Ceiling MaterialSuspended Ceiling Panels

Toilet: Toilet



General: # of Items

2





Sink: # of sinks

1





Observations

14.4.1 GFCI & AFCI

NO GFCI PROTECTION INSTALLED



No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Here is a link to read about how GFCI receptacles keep you safe.



14.5.1 Exhaust Systems

VENT NEEDS CLEANING





14.6.1 Floors

DAMAGED (GENERAL)



The floor had general moderate damage visible at the time of the inspection. Recommend service by a qualified contractor.





14.6.2 Floors **FLOORING POSSIBLY ASBESTOS**





15: LOBBY

		IN	NI	NP	D
15.1	General	Χ	141	141	
15.2	Heating/ Cooling	Χ			
15.3	Lighting Fixtures, Switches & Receptacles	Χ			
15.4	Floors	Χ			
15.5	Windows	Χ			Χ
15.6	Walls	Χ			
15.7	Ceilings	Χ			
15.8	Doors	Χ			
15.9	Closets			Χ	
15.10	Smoke Detectors			Χ	


Information

Heating/ Cooling: Heating Cooling Windows: Window Material Walls: Wall Material

Source Wood Drywall

Ceilings: Ceiling MaterialSuspended Ceiling Panels

General: LocationMain Floor





Floors: Floor Coverings

Tile





Windows: Window Type

Double-hung









Observations

15.5.1 Windows

MISSING SCREEN

Window missing screen. Recommend replacement.











15.5.2 Windows

BROKEN GLASS





15.5.3 Windows

WINDOW IS SCREWED SHUT











16: OFFICE

		IN	NI	NP	D
16.1	General	Χ			
16.2	Heating/ Cooling	Χ			
16.3	Lighting Fixtures, Switches & Receptacles	Χ			
16.4	Floors	Χ			
16.5	Windows	Χ			
16.6	Walls	Χ			Χ
16.7	Ceilings	Χ			
16.8	Doors	Χ			
16.9	Closets	Χ			Χ
16.10	Smoke Detectors			Χ	

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings
Source Carpet



Walls: Wall MaterialDrywall

Windows: Window TypeFixed




Ceilings: Ceiling MaterialSuspended Ceiling Panels

General: LocationMain Floor

Metal

Windows: Window Material





Observations

16.6.1 Walls

MINOR CRACKS





16.6.2 Walls

DAMAGE





16.9.1 Closets

MINOR DAMAGE





17: MAIN FLOOR HALLWAY

		IN	NI	NP	D
17.1	General	Χ			
17.2	Heating/ Cooling			Χ	
17.3	Lighting Fixtures, Switches & Receptacles	Χ			
17.4	Floors	Χ			
17.5	Windows			Χ	
17.6	Walls	Χ			Χ
17.7	Ceilings	Χ			
17.8	Doors	Χ			
17.9	Closets			Χ	
17.10	Smoke Detectors			Χ	

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiency

Not Present

Windows: Window Type

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings Tile Source



Walls: Wall Material

Ceilings: Ceiling Material Suspended Ceiling Panels Drywall

General: Location Main Floor

Not Present

Windows: Window Material





Observations

17.6.1 Walls

MINOR CRACKS

Minor cracks





18: MAIN FLOOR HALLWAY 2

		IN	NI	NP	D
18.1	General	Χ			
18.2	Heating/ Cooling			Χ	
18.3	Lighting Fixtures, Switches & Receptacles	Χ			Χ
18.4	Floors	Χ			
18.5	Windows			Χ	
18.6	Walls	Χ			
18.7	Ceilings	Χ			
18.8	Doors	Χ			
18.9	Closets	Χ			
18.10	Smoke Detectors	Χ			

IN = Inspected

NI = Not Inspected NP = Not Present

D = Deficiency

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings Source Carpet



Walls: Wall Material Drywall

General: Location Main Floor

Not Present

Windows: Window Material





Windows: Window Type Not Present

Ceilings: Ceiling Material Suspended Ceiling Panels

Observations

18.3.1 Lighting Fixtures, Switches & Receptacles



DAMAGED RECEPTACLE

Recommend replacement.



19: FOYER

		IN	NI	NP	D
19.1	General	Χ			
19.2	Heating/ Cooling	Χ			
19.3	Lighting Fixtures, Switches & Receptacles	Χ			
19.4	Floors	Χ			
19.5	Windows			Χ	
19.6	Walls	Χ			
19.7	Ceilings	Χ			
19.8	Doors	Χ			
19.9	Closets			Χ	
19.10	Smoke Detectors			Χ	

Not Present

Windows: Window Type

Information

Heating/ Cooling: Heating Cooling Floors: Floor Coverings
Source
Tile



Walls: Wall MaterialDrywall

Ceilings: Ceiling Material
Suspended Ceiling Panels

General: LocationMain Floor

Not Present

Windows: Window Material





STANDARDS OF PRACTICE

Roof

I. The inspector shall inspect from ground level or the eaves: A. the roof-covering materials; B. the gutters; C. the downspouts; D. the vents, flashing, skylights, chimney, and other roof penetrations; and E. the general structure of the roof from the readily accessible panels, doors or stairs. II. The inspector shall describe: A. the type of roof-covering materials. III. The inspector shall report as in need of correction: A. observed indications of active roof leaks. IV. The inspector is not required to: A. walk on any roof surface. B. predict the service life expectancy. C. inspect underground downspout diverter drainage pipes. D. remove snow, ice, debris or other conditions that prohibit the observation of the roof surfaces. E. move insulation. F. inspect antennae, satellite dishes, lightning arresters, de-icing equipment, or similar attachments. G. walk on any roof areas that appear, in the inspectors opinion, to be unsafe. H. walk on any roof areas if doing so might, in the inspector's opinion, cause damage. I. perform a water test. J. warrant or certify the roof. K. confirm proper fastening or installation of any roof-covering material.

Exterior

I. The inspector shall inspect: A. the exterior wall-covering materials, flashing and trim; B. all exterior doors; C. adjacent walkways and driveways; D. stairs, steps, stoops, stairways and ramps; E. porches, patios, decks, balconies and carports; F. railings, guards and handrails; G. the eaves, soffits and fascia; H. a representative number of windows; and I. vegetation, surface drainage, retaining walls and grading of the property, where they may adversely affect the structure due to moisture intrusion. II. The inspector shall describe: A. the type of exterior wall-covering materials. III. The inspector shall report as in need of correction: A. any improper spacing between intermediate balusters, spindles and rails. IV. The inspector is not required to: A. inspect or operate screens, storm windows, shutters, awnings, fences, outbuildings, or exterior accent lighting. B. inspect items that are not visible or readily accessible from the ground, including window and door flashing. C. inspect or identify geological, geotechnical, hydrological or soil conditions. D. inspect recreational facilities or playground equipment. E. inspect seawalls, breakwalls or docks. F. inspect erosion-control or earth-stabilization measures. G. inspect for safety-type glass. H. inspect underground utilities. I. inspect underground items. J. inspect wells or springs. K. inspect solar, wind or geothermal systems. L. inspect swimming pools or spas. M. inspect wastewater treatment systems, septic systems or cesspools. N. inspect irrigation or sprinkler systems. O. inspect drainfields or dry wells. P. determine the integrity of multiple-pane window glazing or thermal window seals.

Basement, Crawlspace & Structure

I. The inspector shall inspect: A. the foundation; B. the basement; C. the crawlspace; and D. structural components. II. The inspector shall describe: A. the type of foundation; and B. the location of the access to the under-floor space. III. The inspector shall report as in need of correction: A. observed indications of wood in contact with or near soil; B. observed indications of active water penetration; C. observed indications of possible foundation movement, such as sheetrock cracks, brick cracks, out-of-square door frames, and unlevel floors; and D. any observed cutting, notching and boring of framing members that may, in the inspector's opinion, present a structural or safety concern. IV. The inspector is not required to: A. enter any crawlspace that is not readily accessible, or where entry could cause damage or pose a hazard to him/herself. B. move stored items or debris. C. operate sump pumps with inaccessible floats. D. identify the size, spacing, span or location or determine the adequacy of foundation bolting, bracing, joists, joist spans or support systems. E. provide any engineering or architectural service. F. report on the adequacy of any structural system or component.

Attic

I. The inspector shall inspect: A. insulation in unfinished spaces, including attics, crawlspaces and foundation areas; B. ventilation of unfinished spaces, including attics, crawlspaces and foundation areas; and C. mechanical exhaust systems in the kitchen, bathrooms and laundry area. II. The inspector shall describe: A. the type of insulation observed; and B. the approximate average depth of insulation observed at the unfinished attic floor area or roof structure. III. The inspector shall report as in need of correction: A. the general absence of insulation or ventilation in unfinished spaces. IV. The inspector is not required to: A. enter the attic or any unfinished spaces that are not readily accessible, or where entry could cause damage or, in the inspector's opinion, pose a safety hazard. B. move, touch or disturb insulation. C. move, touch or disturb vapor retarders. D. break or otherwise damage the surface finish or weather seal on or around access panels or covers. E. identify the composition or R-value of insulation material. F. activate thermostatically operated fans. G. determine the types of materials used in insulation or wrapping of pipes, ducts, jackets, boilers or wiring. H. determine the adequacy of ventilation.

Electrical

I. The inspector shall inspect: A. the service drop; B. the overhead service conductors and attachment point; C. the service head, gooseneck and drip loops; D. the service mast, service conduit and raceway; E. the electric meter and base; F. service-entrance conductors; G. the main service disconnect; H. panelboards and over-current protection devices (circuit breakers and fuses); I. service grounding and bonding; J. a representative number of switches, lighting fixtures and receptacles, including receptacles observed and deemed to be arc-fault circuit interrupter (AFCI)-protected using the AFCI test button, where possible; K. all ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCIs using a GFCI tester, where possible; and L. smoke and carbon-monoxide detectors. II. The inspector shall

describe: A. the main service disconnect's amperage rating, if labeled; and B. the type of wiring observed. III. The inspector shall report as in need of correction: A. deficiencies in the integrity of the serviceentrance conductors insulation, drip loop, and vertical clearances from grade and roofs; B. any unused circuit-breaker panel opening that was not filled; C. the presence of solid conductor aluminum branch-circuit wiring, if readily visible; D. any tested receptacle in which power was not present, polarity was incorrect, the cover was not in place, the GFCI devices were not properly installed or did not operate properly, evidence of arcing or excessive heat, and where the receptacle was not grounded or was not secured to the wall; and E. the absence of smoke detectors. IV. The inspector is not required to: A. insert any tool, probe or device into the main panelboard, sub-panels, distribution panelboards, or electrical fixtures. B. operate electrical systems that are shut down. C. remove panelboard cabinet covers or dead fronts. D. operate or re-set over-current protection devices or overload devices. E. operate or test smoke or carbon-monoxide detectors or alarms F. inspect, operate or test any security, fire or alarms systems or components, or other warning or signaling systems. G. measure or determine the amperage or voltage of the main service equipment, if not visibly labeled. H. inspect ancillary wiring or remote-control devices. I. activate any electrical systems or branch circuits that are not energized. J. inspect low-voltage systems, electrical de-icing tapes, swimming pool wiring, or any timecontrolled devices. K. verify the service ground. L. inspect private or emergency electrical supply sources, including, but not limited to: generators, windmills, photovoltaic solar collectors, or battery or electrical storage facility. M. inspect spark or lightning arrestors. N. inspect or test de-icing equipment. O. conduct voltage-drop calculations. P. determine the accuracy of labeling. Q. inspect exterior lighting.